Approved For Release 2001/00 SECURITY INFORMATION

Chief, Ceneral Services

the building.

Chief, Physical Security Branch

Revised Plans for Record Center

1. This Branch has been advised by Mr. Chief,
Space, Maintenance and Facilities Division, that the original plan
of turning the Cinder Block Muilding into a Record Center vault has
been cancelled pending the construction of a building located at
to house this operation. For a period
of approximately one year the Record Center will be housed in the
Cinder Block Building, located at
on a temporary basis. No TOP SECUET material will be stored within

2. The attached revised floor plan and security recommendations are submitted for your consideration.

This door should be a. Equip front entrance door with a mushroom pin tumbler replaced with fluch key lock having a dead lock type bolt that requires a key to panel type. Present operate the lock from either side of the door.

door very flinsy.

- Equip this door with a 10" x 10" glass covered inspection opening to be centered five feet above the floor.
- Install electric light over the exterior side of this door.

Install push button adjacent to exterior of door, and bell at floated Post.

b. Secure two overhead doors, one located on the east side and one located on the south side of the building, with padlocks. This can be accomplished by drilling a hole through the metal guide track immediately above a guide wheel and inserting the lock shackle. Padlock keys to be placed in glass covered box located adjacent to doors.

3 overhead doors at present.

c. Equip emergency door located in the north end of the building with metal brackets and a 2" x 1;" wooden bar. Provide metal pins to hold bar in place.

- d. Cover all existing windows with expanded metal. Metal may be applied over interior side of windows and secured by means of 21 x 3/4 wood framing.
- e. Install expanded motal or hardware cloth as shown by red lines on floor plan. Metal to extend from floor to a

Approved For Release 2001/08/08: SECURITY INFORMATION

25X1A6a

Approved For Release 2001/06/35 101A-RDP70-00211R000100200016-0 SECURITY INFORMATION

height of eight feet and be roofed over with same material. Required doors to meet operational needs may be installed in corridor walls. These doors to be padlocked so that the building guard may enter the storage areas in the event of an emergency. Pedlocks to be keyed alike and one key placed in a glass covered box and to be located near the guard post.

f. Relocate hand operated fire alarm bell to a point adjacent to the guard post.

Inspection opening not required. Office has windows which will be covered by expanded metal.

15 fixtures to be operative from master switch.

Inspection opening g. Install an 8" x 8" glass covered inspection opening not required. Office in the east wall of the office area. Install light switch has windows which adjacent to opening.

- h. Install a master electric light switch near the guard post so that the guard can control lighting over the entire storage area.
 - i. Install key lock in main office door.
- j. One, twent; -four hour, seven days a week, Guard Post will be established.

25X1A9a

25X1A9a

cc: Addressee. Fr. File (2)